

Serial No. 10/729,288

1 **AMENDMENTS TO THE ABSTRACT OF THE**
2 **DISCLOSURE**
3

4 A protector for vehicles' door openings, with hingedly mounted
5 doors to cover an adjacent area and protect it from rain and snow. The
6 protector includes at least one frustro-conical roller member with a rollable
7 sheet. The rollable sheet has two straight lateral ends and two curved
8 lateral ends. Male and female hook members means for removably
9 mounting ~~said second lateral~~ one of the straight lateral ends end to the
10 upper end of ~~said the~~ door so that when ~~said the~~ door is swung open ~~said~~
11 the rollable sheet is unrolled substantially covering the area adjacent to
12 said ~~the~~ door's opening. Each frustro-conical roller member includes
13 spring bias assembly for urging the rolling back of the rollable sheet after
14 being rolled out. When at least two roller members and at least two
15 rollable sheets are contiguous, the rollable sheets include a zipper member
16 means for releasably joining the contiguous curved lateral ends.

17

18

BEST AVAILABLE COPY

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.